<u>CARR</u> - 393


THOMAS JONES LOG HOUSE

mid-19th century

Meadow Branch Road Westminster vicinity

private

The Thomas Jones Log House is a deteriorated structure located on the east side of Meadow Branch Road, approximately one-quarter mile north of the Taneytown Pike. The house is a one-story log structure covered in weatherboard. It is built into a bank with a full level on the store foundation's main facade. The appearance of the house suggests a mid-nineteenth century date for the structure. The Martenet's Map of 1862 shows that it was owned by a black man named Thomas Jones. The house has not been lived in for about fifteen years and is probably beyond rehabilitation.



COUNTY:

LOCATION:

COMMON NAME:

FUNCTIONAL TYPE: house

ACCESSIBILITY TO PUBLIC:

LEVEL OF SIGNIFICANCE:

TOWN:

OWNER:

ADDRESS:

## WESTMINSTER PLANNING DISTRICT

	SUFVEY NUMBER: (ARR - 393
DEPARTMENT OF PLANNING AND DEVELOPMENT	NEGATIVE FILE NUMBER:
225. N. Center Street Westminster, Maryland 21157	UTM REFERENCES: Zone/Easting/Northing
WESTMINSTER PLANNING DISTRICT	
FIELD SHEETHISTORIC RESOURCES SURVEY	U.S.G.S. QUAD. MAP: New Windsor
	PRESENT FORMAL NAME:
JNTY: CARROLL	ORIGINAL FORMAL NAME:
M: Westmista v.c.  CATION: eart side of Meadow Breach Road:	PRESENT USE: daelict
	ORIGINAL USE: Vesidace
MAP 38 Block 16 P-359 H Tareytown Pilce	ARCHITECT/ENGINEER:
MON NAME: Thomas Jones Log House	BUILDER/CONTRACTOR:
CTIONAL TYPE: house	
IER: Louise R. Knight	PHYSICAL CONDITION OF STRUCTURE:
RESS:	Excellent ( ) Good ( )
	Fair ( ) Poor (×)
ESSIBILITY TO PUBLIC:	THEME:
() No (X) Restricted () EL OF SIGNIFICANCE:	STYLE:
al ( ) State ( ) National ( )	DATE BUILT: enid-nineteenth century
Aluminum ( ) Asphalt Shing Bonding Pattern:	
A. Truss: Wood (X) Iron ( ) Steel ( )	Concrete ( )
B. Other: 5. Roof Covering: Slate () Wood Shingle () Built Up () Rolled () To 6. Engineering Structure:	Asphalt Shingle ( ) Sheet Metal ( )
7. Other: pendages: Porches (X) Towers () Cupolas () Ells (X) Wings () Other:	Dormers ( ) Chimneys ( ) Sheds ( )
of Style: Gable (X) Hip () Shed () Flat ( Saw Tooth () With Monitor () With With False Front () Other: mber of Stories:	) Mansard ( ) Gambrel ( ) Jerkinhead ( ) n Bellcast ( ) With Parapet ( )
mber of Bays: 3 x 2	Entrance Location: Side
proximate Dimensions:	recorded to the control of the contr
	dorwenty hart West Augustoperance Up ( )
REAT TO STRUCTURE:	LOCAL ATTITUDES:
Threat ( ) Zoning ( ) Roads ( )	Positive ( ) Negative ( )
velopment ( ) Deterioration ( )	Mixed ( ) Other:
teration ( ) Other:	

5/9 house might on house

AREAT TO STRUCTURE: No Threat ( ) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:

Open Lane ()Woodland ()Scattered Buildings()
Moderately Built Up ()Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:


Joe Cetty

ORGANIZATION:

Can. Co. Planning Dept

DATE RECORDED:

August 1963





- 1. CARR-393 LOG HOUSE
- 2. Carroll County, Maryland
- 3. Joe Getty
- 4. November 1983
- 5. Md. Historical Trust, Annapolis, Md.)
- 6. North elevation (camera facing south)
- 7. 1/1